

4. COMPILED PHOTOGRAPHS

PHOTOGRAPHIC DOCUMENTATION

In order to analyze the existing nature and condition of the Capitol, several hundred professional architectural photographs were taken of the Capitol, the campus of buildings and grounds. Included in this extensive documentation are overall perspective views of the exterior and interior, elevational (head-on) views of the key exterior and interior walls, plus close-up views of a large number of architectural details. Included in this latter category are views of deteriorated, damaged or altered exterior and interior elements. Moore's photos are found throughout all sections of the report to illustrate the information presented in the narrative text. Because of the great number of photos taken and the limited space available in the report, many of the photos are not included in the report. All of the photos, including the unused ones, are on compact disks that will be given to the Capitol Preservation Board for placement in its archives.



In addition, the architects used digital cameras to take photos of each room in the Capitol, as well as selected details. These photos are found in the exterior and interior survey forms. The historical sections of the text were illustrated through the use of historical photos copied from originals found in such locations as the State Historical Society Library and State Archives. The Cooper/Roberts collection of photos also will be made available to the state. Similarly, photos taken by the team's consultants for their sections of the report will be made available.

Given the constraints in the length of this study and its set of final report documents, we were unable to include all of the written, photographic and graphic material we collected during the process of preparing the report. It is our intent, however, to make this material available in ways that will continue to advance the project



